

FIG. 2

REPLACEMENT SHEET

2/5




FIG. 5




FIG. 3




FIG. 4

REPLACEMENT SHEET

3/5

TRANSDUCER STABILITY: DUT ERROR RELATIVE TO A CAPACITANCE DIAPHRAGM GAGE REFERENCE






FIG. 6

REPLACEMENT SHEET

4/5



REPLACEMENT SHEET

5/5

FIG. 7C




FIG. 7D

